## **LMA District Cover Sheet**

### **Spring 2009 Levee Inspection Results**

# **Reclamation District No. 0349**

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
* Overall LMA Rating (Fall Only)				
	** Non-receipt of Su	mmer or Winter Inspe	ection Reports may effec	ct overall annual rating.
	d using the same crite	ria in the spring and in	the fall.	
FALL INSPECTIONS: The overall maintena within the attached u	nit inspection reports.	ve is based on operati	on and maintenance de	ficiencies identified
Comments				

### **Unit Cover Sheet**

### **Spring 2009 Levee Inspection Results**

# **Reclamation District No. 0349**

Waterway Bank Unit Mile Unit No. 01 Sacramento River Right 1.60											
	Unit No. 01 Saci	amento River		Rigiit	1.00						
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - Februa							
Unit Maintenance Rating (Fall Only)											
Date of Inspection	5/8/2009 - 5/8/2009										
DWR Inspector	Herman Phillips										
Accompanied By											
Check one:											
<ul> <li>During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.</li> <li>During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.</li> <li>(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).</li> </ul>											
information must also be DWR with any additional	3:	eet should be signed an	d dated by the LMA Represer th 31 (Winter Inspection). Plea spection Reports , Room LL-30	ntative an	d returned to						

X

## Levee Inspection Report By Mile - Spring 2009

# **Reclamation District No. 0349**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.60	05/08/2009 05/08/2009	Herman Phillips

LMR Line	Levee	Mile	Category	Item	Location *	Rating	Action/Comment		Issue
1	0.00	0.03	Earthen Levee	Encroachments	WS	СО	Landscaping	38.327135 ° 38.326607 ° -121.577118 ° -121.577132 °	1
2	0.13	0.26	Earthen Levee	Vegetation	WS	М	Control annual grass and weeds on the levee slopes and easements.	38.325323 ° 38.323468 ° -121.577565 ° -121.578140 °	20
3	0.14	0.25	Earthen Levee	Vegetation	LS	М	Control annual grass and weeds on the levee slopes and easements.	38.325153 ° 38.323550 ° -121.577620 ° -121.578098 °	21
4	0.38	0.39	Earthen Levee	Vegetation	WS	С	Control annual grass and weeds on the levee slopes and easements.	38.321807 ° 38.321595 ° -121.578535 ° -121.578602 °	22
5	0.38	0.40	Earthen Levee	Vegetation	WS	С	Remove the wild growth other than native grasses from the levee slopes.	38.321727 ° 38.321493 ° -121.578473 ° -121.578588 °	4
6	0.42	0.48	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.321207 ° 38.320352 ° -121.578663 ° -121.578755 °	23
7	0.48	0.48	Earthen Levee	Encroachments	LS	M	Tank	38.320282 ° 38.320277 ° -121.578688 ° -121.578683 °	7
8	0.51	0.66	Earthen Levee	Trim / Thin Trees	LS	М	Trim trees to at least five feet above ground level.	38.319928 ° 38.317708 ° -121.578782 ° -121.579072 °	8
9	0.62	0.68	Earthen Levee	Vegetation	LS	С	Control annual grass and weeds on the levee slopes and easements.	38.318395 ° 38.317538 ° -121.579033 ° -121.579248 °	24
10	0.74	0.74	Earthen Levee	Encroachments	LS	СО	Landscaping	38.316670 ° 38.316670 ° -121.579052 ° -121.579052 °	12
11	0.93	0.98	Earthen Levee	Vegetation	LS	С	Control annual grass and weeds on the levee slopes and easements.	38.313823 ° 38.313218 ° -121.579007 ° -121.578977 °	25
12	1.05	1.06	Earthen Levee	Trim / Thin Trees	LS	С	Trim trees to at least five feet above ground level.	38.312172 ° 38.312112 ° -121.578495 ° -121.578458 °	14
13	1.36	1.41	Earthen Levee	Trim / Thin Trees	LS	С	Trim trees to at least five feet above ground level.	38.308113 ° 38.307478 ° -121.576252 ° -121.575790 °	16
14	1.45	1.45	Earthen Levee	Encroachments	LS	РО	Landscaping	38.307075 ° 38.307073 ° -121.575485 ° -121.575487 °	17
15	1.45	1.56	Earthen Levee	Vegetation	LS	С	Remove the wild growth other than native grasses from the levee slopes.	38.307075 ° 38.305583 ° -121.575485 ° -121.574755 °	18
16	1.56	1.59	Earthen Levee	Vegetation	WS	М	Remove the wild growth other than native grasses from the levee slopes.	38.305580 ° 38.305210 ° -121.574757 ° -121.574803 °	19

\* Location LS : Land Side WS : Water Side CR : Crown

\*\* Rating

A : Acceptable M : Minimally Acceptable U : Unacceptable PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected

### **Unit Cover Sheet**

## **Spring 2009 Levee Inspection Results**

# **Reclamation District No. 0349**

	Water	way		Bank	Unit Miles					
	Unit No. 02 Stea	mboat Slough		Right	4.40					
	Spring (March - May)	Summer (June - August)	(September - November) Fall		Winter ber - February)					
Unit Maintenance Rating (Fall Only)										
Date of Inspection	5/1/2009 - 5/1/2009									
DWR Inspector	Herman Phillips									
Accompanied By										
Check one:										
project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.  During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.  (In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).										
Comments One of the boxes above is	s to be checked by the Local M	laintaining Agency (LM	A). If the second box is checke	ed, additio	onal					
	3		ch 31 (Winter Inspection). Plea spection Reports s, Room LL-30							

X

Signature of LMA Representative

Date

## Levee Inspection Report By Mile - Spring 2009

# **Reclamation District No. 0349**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Steamboat Slough	Right	4.40	05/01/2009 05/01/2009	Herman Phillips

LMR Line	Levee	Mile End	Category	Item	Location *	Rating	Action/Comment	GPS Latitude/Longitude Start End	Issue
1	0.03	0.07	Earthen Levee	Vegetation	WS	М	Remove the wild growth other than native grasses from the levee slopes.	38.304935 ° 38.304798 ° -121.575325 ° -121.575920 °	2
2	0.04	0.06	Earthen Levee	Vegetation	WS	M	Remove the wild growth other than native grasses from the levee slopes.	38.304873 ° 38.304873 ° -121.575517 ° -121.575815 °	1
3	0.05	0.12	Earthen Levee	Vegetation	LS	С	Control annual grass and weeds on the levee slopes and easements.	38.304915 ° 38.304445 ° -121.575642 ° -121.576782 °	63
4	0.10	0.11	Earthen Levee	Encroachments	LS	С	Equipment	38.304558 ° 38.304580 ° -121.576423 ° -121.576630 °	4
5	0.11	0.14	Earthen Levee	Vegetation	LS	С	Remove the wild growth other than native grasses from the levee slopes.	38.304503 ° 38.304278 ° -121.5776572 ° -121.577127 °	5
6	0.11	0.12	Earthen Levee	Encroachments	LS	С	Tree or limb	38.304607 ° 38.304442 ° -121.576715 ° -121.576783 °	64
7	0.12	0.17	Earthen Levee	Vegetation	WS	М	Remove the wild growth other than native grasses from the levee slopes.	38.304480 ° 38.304002 ° -121.576747 ° -121.577460 °	65
8	0.21	0.25	Earthen Levee	Encroachments	LS	РО	Landscaping	38.303673 ° 38.303303 ° -121.578065 ° -121.578695 °	7
9	0.24	0.27	Earthen Levee	Encroachments	LS	РО	Fences	38.303390 ° 38.303157 ° -121.578577 ° -121.578962 °	8
10	0.28	0.34	Earthen Levee	Trim / Thin Trees	LS	С	Trim trees to at least five feet above ground level.	38.303060 ° 38.302432 ° -121.579162 ° -121.579965 °	9
11	0.38	0.38	Boat Survey	Boat Survey Erosion	LS	М	Inspector Comments: tree hazards	38.302317 ° 38.301732 ° -121.530008 ° -121.579627 °	966
12	0.38	0.50	Earthen Levee	Vegetation	LS	С	Remove the wild growth other than native grasses from the levee slopes.	38.302113 ° 38.300358 ° -121.580588 ° -121.580970 °	66
13	0.82	0.83	Earthen Levee	Trim / Thin Trees	LS	С	Trim trees to at least five feet above ground level.	38.296008 ° 38.295862 ° -121.582838 ° -121.582900 °	68
14	0.82	0.83	Earthen Levee	Encroachments	LS	М	Material	38.296005 ° 38.295862 ° -121.582838 ° -121.582900 °	67
15	0.84	0.90	Earthen Levee	Vegetation	LS	М	Remove the wild growth other than native grasses from the levee slopes.	38.295753 ° 38.294985 ° -121.582838 ° -121.583147 °	12
16	0.86	0.91	Earthen Levee	Trim / Thin Trees	LS	С	Trim trees to at least five feet above ground level.	38.295550 ° 38.294800 ° -121.582997 ° -121.583345 °	69
17	0.92	1.32	Earthen Levee	Vegetation	LS	М	Remove the wild growth other than native grasses from the levee slopes.	38.294668 ° 38.289050 ° -121.583362 ° -121.584140 °	70

\* Location LS : Land Side WS : Water Side CR : Crown

Friday, June 05, 2009 09:51

\*\* Rating

A : Acceptable M : Minimally Acceptable U : Unacceptable PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected

## Levee Inspection Report By Mile - Spring 2009

# **Reclamation District No. 0349**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Steamboat Slough	Right	4.40	05/01/2009 05/01/2009	Herman Phillips

LMR Line	Levee	Mile End	Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude	Issue
18	0.93	0.95	Earthen Levee	Vegetation	WS	М	Remove the wild growth other than native grasses from the levee slopes.	38.294472 ° 38.294242 ° -121.583362 ° -121.583398 °	71
19	1.08	1.31	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.292413 ° 38.289147 ° -121.583823 ° -121.583962 °	17
20	1.10	1.10	Earthen Levee	Encroachments	WS	С	Prunings	38.292123 ° 38.292123 ° -121.583907 ° -121.583907 °	16
21	1.11	1.11	Earthen Levee	Encroachments	WS	С	Garbage	38.292030 ° 38.291970 ° -121.584077 ° -121.584095 °	72
22	1.33	1.34	Earthen Levee	Encroachments	LS	РО	Landscaping	38.288913 ° 38.288745 ° -121.583933 ° -121.583938 °	18
23	1.34	1.36	Earthen Levee	Encroachments	WS	С	Prunings	38.288672 ° 38.288458 ° -121.583943 ° -121.583955 °	19
24	1.41	1.61	Earthen Levee	Vegetation	WS	М	Remove the wild growth other than native grasses from the levee slopes.	38.287717 ° 38.285738 ° -121.584145 ° -121.586830 °	73
25	1.43	1.60	Earthen Levee	Vegetation	LS	М	Control annual grass and weeds on the levee slopes and easements.	38.287377 ° 38.285832 ° -121.584325 ° -121.586647 °	74
26	1.62	1.66	Earthen Levee	Encroachments	LS	С	Prunings	38.285457 ° 38.285150 ° -121.586903 ° -121.587463 °	22
27	1.70	1.73	Earthen Levee	Vegetation	LS	С	Control annual grass and weeds on the levee slopes and easements.	38.284840 ° 38.284550 ° -121.587990 ° -121.588370 °	75
28	1.77	1.80	Earthen Levee	Vegetation	LS	С	Control annual grass and weeds on the levee slopes and easements.	38.284130 ° 38.283727 ° -121.588798 ° -121.589105 °	76
29	1.80	1.83	Earthen Levee	Encroachments	LS	СО	Landscaping	38.283698 ° 38.283400 ° -121.589143 ° -121.589273 °	25
30	1.82	1.82	Earthen Levee	Vegetation	LS	С	Remove the wild growth other than native grasses from the levee slopes.	38.283475 ° 38.283475 ° -121.589340 ° -121.589340 °	27
31	1.86	1.99	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.282917 ° 38.281143 ° -121.589500 ° -121.589718 °	77
32	2.13	2.15	Boat Survey	Boat Survey Erosion	LS	М	Inspector Comments: tree hazards	38.278985 ° 38.278565 ° -121.589528 ° -121.589767 °	963
33	2.32	2.32	Earthen Levee	Encroachments	WS	С	Garbage	38.286093 ° 38.286093 ° -121.604830 ° -121.604830 °	51
34	2.37	2.41	Earthen Levee	Vegetation	LS	С	Remove the wild growth other than native grasses from the levee slopes.	38.275857 ° 38.275503 ° -121.591717 ° -121.591257 °	78

\* Location LS : Land Side WS : Water Side CR : Crown

A : Acceptable M : Minimally Acceptable U : Unacceptable PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected

## Levee Inspection Report By Mile - Spring 2009

# **Reclamation District No. 0349**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Steamboat Slough	Right	4.40	05/01/2009 05/01/2009	Herman Phillips

35	2.41 2.69	End 2.44	Category	Item	Location *	Rating	Action/Comment		
36		2.44	Farthen					Start Life	Issue
	2.69		Levee	Encroachments	LS	PO	Landscaping	38.275492 ° 38.275092 ° -121.591268 ° -121.590910 °	31
37		3.02	Earthen Levee	Vegetation	LS	М	Control annual grass and weeds on the levee slopes and easements.	38.272323 ° 38.267912 ° -121.5889553 ° -121.588910 °	79
	2.70	2.72	Earthen Levee	Vegetation	LS	М	Remove the wild growth other than native grasses from the levee slopes.	38.272228 ° 38.272017 ° -121.589695 ° -121.589818 °	34
38	2.75	2.75	Earthen Levee	Encroachments	LS	С	Tree or limb	38.271588 ° 38.271588 ° -121.589898 ° -121.589898 °	35
39	2.77	3.02	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.271213 ° 38.267830 ° -121.589877 ° -121.588897 °	36
40	3.03	3.07	Earthen Levee	Trim / Thin Trees	LS	С	Thin trees to allow visibility of the ground and room to flood fight.	38.267742 ° 38.267263 ° -121.588848 ° -121.588487 °	37
41	3.07	3.10	Earthen Levee	Encroachments	LS	СО	Landscaping	38.267265 ° 38.266747 ° -121.588470 ° -121.588355 °	38
42	3.11	3.27	Earthen Levee	Vegetation	LS	М	Remove the wild growth other than native grasses from the levee slopes.	38.266665 ° 38.264297 ° -121.588437 ° -121.588315 °	39
43	3.19	3.21	Earthen Levee	Encroachments	LS	С	Prunings	38.265427 ° 38.265097 ° -121.588318 ° -121.588322 °	40
44	3.64	3.72	Earthen Levee	Trim / Thin Trees	LS	М	Trim trees to at least five feet above ground level.	38.262322 ° 38.261483 ° -121.593935 ° -121.594867 °	43
45	3.73	4.35	Earthen Levee	Vegetation	LS	М	Remove the wild growth other than native grasses from the levee slopes.	38.261432 ° 38.254770 ° -121.594890 ° -121.600022 °	44
46	3.73	3.74	Earthen Levee	Encroachments	WS	РО	Landscaping	38.261403 ° 38.261330 ° -121.594932 ° -121.595022 °	45
47	3.73	3.77	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.261403 ° 38.260820 ° -121.594963 ° -121.595152 °	80
48	3.74	3.75	Earthen Levee	Encroachments	LS	U	Pipe	38.261297 ° 38.261190 ° -121.595008 ° -121.595107 °	46
49	3.75	3.77	Earthen Levee	Encroachments	LS	U	Equipment	38.261242 ° 38.260868 ° -121.595173 ° -121.595267 °	47
50	3.78	3.78	Earthen Levee	Encroachments	LS	РО	Urban	38.260823 ° 38.260705 ° -121.595253 ° -121.595275 °	48
51	4.34	4.35	Earthen Levee	Vegetation	WS	М	Remove the wild growth other than native grasses from the levee slopes.	38.254760 ° 38.254880 ° -121.599925 ° -121.600070 °	81

\* Location LS : Land Side WS : Water Side CR : Crown \*\* Rating

A : Acceptable M : Minimally Acceptable U : Unacceptable PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected

### **Unit Cover Sheet**

### **Spring 2009 Levee Inspection Results**

# **Reclamation District No. 0349**

Waterway Bank Unit Mile Unit No. 03 Sutter Slough Left 6.60											
	Onit No. 03 30	itter Slough		Leit	0.00						
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - Febru							
Unit Maintenance Rating (Fall Only)											
Date of Inspection	5/1/2009 - 5/1/2009										
DWR Inspector	Herman Phillips										
Accompanied By											
Check one:											
<ul> <li>During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.</li> <li>During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.</li> <li>(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).</li> </ul>											
information must also be s	3	eet should be signed an	nd dated by the LMA Represent ch 31 (Winter Inspection). Pleast spection Reports Room LL-30	itative an	d returned to						

X

Signature of LMA Representative

Date

## Levee Inspection Report By Mile - Spring 2009

# **Reclamation District No. 0349**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Sutter Slough	Left	6.60	05/01/2009 05/01/2009	Herman Phillips

LMR Line	Levee	Mile End	Category	Item	Location *	Rating	Action/Comment	GPS Latitude/Longitude	Issue
1	0.05	0.79	Earthen Levee	Vegetation	LS	М	Control annual grass and weeds on the levee slopes and easements.	38.255492 ° 38.265955 ° -121.599958 ° -121.601765 °	15
2	0.29	0.92	Earthen Levee	Vegetation	WS	С	Control annual grass and weeds on the levee slopes and easements.	38.258920 ° 38.267728 ° -121.600013 ° -121.602498 °	16
3	0.63	0.63	Earthen Levee	Encroachments	LS	С	Tree or limb	38.263683 ° 38.263683 ° -121.601017 ° -121.601017 °	3
4	0.79	0.85	Earthen Levee	Encroachments	LS	СО	Landscaping	38.265952 ° 38.266842 ° -121.601692 ° -121.602033 °	4
5	0.83	0.84	Earthen Levee	Encroachments	WS	С	Tree or limb	38.266390 ° 38.266557 ° -121.602013 °	17
6	0.99	1.02	Earthen Levee	Encroachments	LS	С	Equipment	38.268692 ° 38.269032 ° -121.603183 °	6
7	1.11	1.12	Earthen Levee	Encroachments	LS	U	Tree or limb	38.270247 ° 38.270477 ° -121.603575 ° -121.603527 °	18
8	1.70	1.76	Earthen Levee	Encroachments	LS	СО	Landscaping	38.278355 ° 38.279095 ° -121.600330 ° -121.600273 °	14
9	1.94	1.94	Earthen Levee	Encroachments	WS	С	Tree or limb	38.281668 ° 38.281668 ° -121.601020 °	19
10	1.98	2.29	Earthen Levee	Vegetation	LS	С	Control annual grass and weeds on the levee slopes and easements.	38.282158 ° 38.285723 ° -121.601470 ° -121.604827 °	20
11	2.02	2.30	Earthen Levee	Vegetation	WS	М	Control annual grass and weeds on the levee slopes and easements.	38.282602 ° 38.285848 ° -121.601882 ° -121.604852 °	21
12	2.53	3.01	Earthen Levee	Vegetation	LS	М	Control annual grass and weeds on the levee slopes and easements.	38.288860 ° 38.295688 ° -121.603258 ° -121.604707 °	22
13	3.06	3.22	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.296288 ° 38.298333 ° -121.604590 ° -121.603127 °	23
14	4.60	4.71	Boat Survey	Boat Survey Erosion	LS	U	Inspector Comments: tree hazards, slumping	38.315408 ° 38.313988 ° -121.591517 ° -121.592222 °	970
15	4.86	5.26	Earthen Levee	Vegetation	LS	М	Control annual grass and weeds on the levee slopes and easements.	38.317223 ° 38.322790 ° -121.589992 ° -121.589232 °	24
16	4.86	6.42	Earthen Levee	Vegetation	WS	М	Control annual grass and weeds on the levee slopes and easements.	38.317223 ° 38.328298 ° -121.589992 ° -121.578785 °	25
17	5.27	5.47	Earthen Levee	Vegetation	CR	U	Control annual grass and weeds on the levee slopes and easements.	38.322790 ° 38.324003 ° -121.589228 ° -121.585907 °	26

Location LS : Land Side WS : Water Side CR : Crown

A : Acceptable M : Minimally Acceptable U : Unacceptable

PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected

## Levee Inspection Report By Mile - Spring 2009

# **Reclamation District No. 0349**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Sutter Slough	Left	6.60	05/01/2009 05/01/2009	Herman Phillips

LMR	Levee	Levee Mile		ltono		Rating	A skip in 100 meno on k	GPS Latitude/Longitude		
Line	Start	End	Category	Item	Location *	ing *	Action/Comment	Start	End	Issue
18	5.30	6.42	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.322945 ° -121.588602 °	38.328300 ° 121.578780 °	27
19	5.44	5.53	Earthen Levee	Trim / Thin Trees	WS	М	Thin trees to allow visibility of the ground and room to flood fight.	38.323783 ° -121.586260 °	38.324857 ° -121.585360 °	28
20	5.60	5.65	Earthen Levee	Vegetation	CR	M	Control annual grass and weeds on the levee slopes and easements.	38.325725 ° -121.584892 °	38.326537 ° -121.584615 °	29